



Site Name: 1/3/2023

Location: 17909 25TH AVE NE  
MARYSVILLE  
Tax ID: 31052000301500  
Use:

**Service Company:**

**A Wesco Septic**  
16607 SR 9 SE  
Snohomish, WA 98296  
360-668-6561

Serviced:11/01/2022 by: Nolan Parker (ID#: 7794)

Submitted 11/01/2022 by:Joe Bush

Tenelco Inc

Jurisdiction ID:31052000301500

**COMMENTS**

Septic tank was pumped for decommission. Aero Construction will crush & back fill.

| <b>TANK: Septic Tank - 2 Compartment</b>  |          |  |
|---|----------|--|
| Tank Pumped:  | YES      |  |
| Tank Size (Gallons)(Number only, no text):                                      | 1000     |  |
| Effluent level within operational limits (if NO explain in comments):           | YES      |  |
| Total Gallons pumped from tank (Number only, no text):                          | 1000     |  |
| Effluent returning back into tank after pumping:                                | NO       |  |
| Tank depth below grade (inches):  | 0        |  |
| Access Risers installed to grade (N/A if not present):                          | NO       |  |
| Tank Construction Material:   | Concrete |  |
| Tank Condition Good:  | YES      |  |
| Baffles in good condition (N/A if not present):                                 | YES      |  |
| Effluent screen cleaned (N/A if not present):                                   | N/A      |  |
| Effluent surfacing around site components (N/A if not checked):                 | NO       |  |
| Tank abandoned after pumping:   | YES      |  |
| Were repairs made to the Tank or Tank Components? (if YES explain in comments): | NO       |  |
| Compartment 1 Scum accumulation (Inches, if other specify):                     | 3        |  |
| Compartment 1 Sludge accumulation (Inches, if other specify):                   | 6        |  |
| Compartment 2 Scum accumulation (Inches, if other specify):                     | 0        |  |
| Compartment 2 Sludge accumulation (Inches, if other specify):                   | 6        |  |